# Work Order Bid (ID)



### **WORK ORDER INFORMATION**

Work Order Name: WO/20002BR-0174/1

Work Order Type: Weatherization

Audit Name: 20002BR-0174AUDIT

#### **CLIENT INFORMATION**

Client ID: 20002BR-0174

#### <u>AGENCY INFORMATION</u>

Agency: Bradley-Cleveland Community Services Agency

Agency Phone: (423) 479-4111

**Address:** 155 Sixth Street SE **Fax:** (423) 479-4113

Company Name & License Number:	
Contractor's Signature:	

#### **COMMENT**

1990 mobile home Approx 1026 sqft

Auditor: Darrell Bloodworth Phone: (423) 505-4585 Email: Darblood@comcast.net

## **Measures**

	ean and service heating a nditioning units.	ınd air		Componen	ts		1	Inspected
Home	owner states that furnace volumer states that AC will not e scope of maintenance pe	ot keep m	obile h	ome cool.	ırm.			
				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
0 Labor	Misc Material	Each	1					
Other Detail								
			Measur	e Sub Total:		] ,	Sub Total:	
Field Notes:  Measure 2 Di	gital Thermostat (ea)			Componen	ts			Inspected
Measure 2 Di	gital Thermostat (ea) ng thermostat in poor state	of repair.		Componen				Inspected
Measure 2 Di Comment Existin	ng thermostat in poor state	·	- Of the	Estimated	<u> </u>	041	Actual	
Measure 2 Di Comment Existin	` ,	of repair. <i>Units</i> Each	<b>Qty</b> 1	•		Qty		Inspected
Measure 2 Di Comment Existin # Material / Labor Heating	ng thermostat in poor state  Description / Comment	Units		Estimated	<u> </u>	Qty	Actual	
Measure 2 Di Comment Existin # Material / Labor Heating Equipment	ng thermostat in poor state  Description / Comment	Units		Estimated	1	Qty	Actual	Total
Measure 2 Di Comment Existin # Material / Labor Heating Equipment	ng thermostat in poor state  Description / Comment	Units		Estimated	1	Qty	Actual	
Measure 2 Di Comment Existin # Material / Labor Heating Equipment	ng thermostat in poor state  Description / Comment	Units Each	1	Estimated	1		Actual	

Measure 3 Rep	olace Window Screens			Componen	ts		ļ	Inspected
Comment Window	ws WD-6,7,8 approx 32x27	7						
				Estimated	•		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Windows	Replace window screen	Each	3					
Other Detail								
			Measur	e Sub Total:		] ,	Sub Total:	
Field Notes:								
	al Ducts			Componen	ts			Inspected
<b>Comment</b> Airseal	supply ducts and AC retur	n to less	than 1	=				
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	<b>Unit Cost</b>	Total	Qty	Unit Cost	Total
1 Insulation	Duct sealing (setup cost)	Each	1					
0 Miscellaneous	Duct Sealing	Each	10					
Supplies	g							
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								

	<i>Measur</i> e 5 Gen	eral Air Sealing			Componen	ts			Inspected
C		two door knobs holes in e o wall) in master bedroom					II		
					Estimated	·		Actual	
#	Material / Labor	Description / Comment	Units	Qty	<b>Unit Cost</b>	Total	Qty	Unit Cost	Total
1	Insulation	General air sealing (setup cost)	Each	1					
10	Miscellaneous Supplies	Infiltration Reduction	See Above	1					
C	Other Detail								
				Measur	e Sub Total:		,	Sub Total:	
	Measure 6 DWI	H Pipe Insulation			Componen  Estimated				Inspected
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Actual Unit Cost	Total
	Insulation	DWH Pipe Insulation	Linear Foot	6		70.00			70147
		costs to add 10' wrap to hot/cold							
2	Labor	DWH Pipe Insulation	Each	1					
3	Other	DWH Pipe Insulation	Each	1					
(	Other Detail						1		
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								

Λ	Measure 7 DW	H Tank Insulation			Componen	ts			Inspected
C	omment								
					Estimated	<u> </u>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DWH Tank Insulation	Each	1					
2	Labor	DWH Tank Insulation	Each	1					
0	ther Detail								
L									
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								
	Measure 8 Bell	y Cellulose Loose			Componen	ts			Inspected
		six holes approx 4'x4' in n	nobile hon	ne bell	-				
		om notes approx			Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Floor Insulation - Celluls,Blwn	Bag	51					
2	Labor	Floor Insulation - Celluls,Blwn	Bag	51					
3	Other	Floor Insulation - Celluls,Blwn	Each	1					
	Miscellaneous	Added Misc Cost	Each	1					
	Supplies								
0	ther Detail	]					] [		
L									
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								
- 1									

	Measure 9 Fix I	mproper Venting (Clot	hes Dryer)		Componen	ts		ı	nspected
C	omment								
					Estimated	<del></del> -		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Equipment	Each	1					
2	Labor	Labor	Each	1					
C	Other Detail						1		
L									
L							] []		
			1	Measur	e Sub Total:		,	Sub Total:	
	Measure 10 Insta	all Bathroom Exhaust I	Fan		Componen	ts		ı	nspected
					Estimated	,		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Bathroom exhaust fan	Each	2					
2	Labor	Labor	Each	2					
C	Other Detail								
L									
			1	Measur	e Sub Total:		] ,	Sub Total:	
	Field Notes:								